

**Flood Control Project Maintenance  
Levee Inspections**

**Fall 2009 Levee Maintenance Deficiency Summary Report**

**Overall LMA & Unit Ratings, including USACE Erosion Survey**

**Sacramento River Basin**

---

<b>ST0010</b>	Overall LMA Rating	Total LMA Miles				
<b>Sutter Maintenance Yard Wadsworth Canal</b>	<b>A</b>	<b>9.32</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Animal Control	0.10		0.10	1.07%	PO Miles	CO Miles
<i>LMA Totals:</i>	0.10	0.00	0.10	1.07%	0.00	0.00
<b>Unit No. 01 Wadsworth Canal</b>	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>4.66</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Animal Control	0.01		0.01	0.22%	PO Miles	CO Miles
<i>Unit Totals:</i>	0.01	0.00	0.01	0.22%	0.00	0.00
<b>Unit No. 02 Wadsworth Canal</b>	Overall Unit Rating	Total Unit Miles				
	<b>A</b>	<b>4.66</b>				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
Animal Control	0.09		0.09	1.93%	PO Miles	CO Miles
<i>Unit Totals:</i>	0.09	0.00	0.09	1.93%	0.00	0.00

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Fall 2009 Levee Inspection Results**

**Sutter Maintenance Yard Wadsworth Canal**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2009 Levee Inspection Results**

**Sutter Maintenance Yard Wadsworth Canal**

Waterway			Bank	Unit Miles
Unit No. 01 Wadsworth Canal			Left	4.66
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	4/2/2009		10/12/2009	
DWR Inspector	Bob Duffey		Bob Duffey	
Accompanied By			Steve Beckley Sutter Yard	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2009**

**Sutter Maintenance Yard Wadsworth Canal**

Waterway					Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Wadsworth Canal					Left	4.66	11/10/2009 11/10/2009	Bob Duffey

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	4.62	4.62	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	39.171055 ° -121.727165 °	39.171055 ° -121.727165 °	1

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Fall 2009 Levee Inspection Results**

**Sutter Maintenance Yard Wadsworth Canal**

Waterway			Bank	Unit Miles
Unit No. 02 Wadsworth Canal			Right	4.66
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			<b>A</b>	
Date of Inspection	4/2/2009		10/12/2009	
DWR Inspector	Bob Duffey		Bob Duffey	
Accompanied By			Steve Beckley Sutter Yard	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Fall 2009**

**Sutter Maintenance Yard Wadsworth Canal**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Wadsworth Canal				Right	4.66	11/10/2009 11/10/2009	Bob Duffey

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	4.55	4.64	Earthen Levee	Animal Control	LS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	39.169725 ° -121.727660 °	39.170893 ° -121.727203 °	3

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected